

FIG. 1




FIG. 2

APPROVED	O. G. FIG.
BY	
DRAFTSMAN	

2 / 10




FIG. 1A

3 / 10




FIG. 2A




FIG. 2B




FIG. 2C




FIG. 2D




FIG. 2E

4 / 10




FIG. 3




FIG. 4




FIG. 5A




FIG. 5B




FIG. 6




FIG. 6A




FIG. 6B




FIG. 6C




FIG. 7A




FIG. 7B




FIG. 7C

7 / 10




FIG. 8




FIG. 9




FIG. 9A

8 / 10

FIG. 8A




FIG. 8B





FIG. 8C








FIG. 10A

FIG. 10B



Wash away excess beads and image

FIG. 10C

Apply sample containing beads,
some settle into wells




FIG. 11